

## CONSTRUCTION EQUIPMENT VOLVO SD115B 236555 - REAR RIGHT FINAL DRIVE



Sample No: VCP262424

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Report Id: RIPTAM [WUSCAR] 04944627 (Generated: 12/20/2023 07:54:57) Rev: 1

Job No:

CAMPI F	INFORMATION			
	INI ONI-IATION		_	
Sample Number		VCP262424		 
Sample Date		09 Mar 2020		 
Machine Hours		2324		 
Oil Hours		1000		 
Oil Changed		Changed		 
Sample Status		NORMAL		 
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	143		 
VISC @ 40 C	CSt	143		 
VOLVO				
CONTAM	IINATION			
Water	%	NEG		 
Silicon	ppm	<b>1</b> 0		 
Sodium	ppm	<b>6</b>		 
Potassium	ppm	<b>■&lt;1</b>		 
	le le			
VOLVO				
WEAR M	IETALS			
Iron	ppm	<b>211</b>		 
Copper	ppm	<b></b>		 
Lead	ppm	<b>0</b>		 
Tin	ppm	<b>■&lt;1</b>		 
Aluminum	ppm	<b>■&lt;1</b>		 
Chromium	ppm	<b>2</b>		 
Molybdenum	ppm	<b>0</b>		 
Nickel	ppm	<1		 
Titanium	ppm	<1		 
Silver	ppm	0		 
Manganese	ppm	<b>6</b>		 
Vanadium	ppm	0		 
	P P			
VOLVO	re .			 
ADDITIV	F2			
Calcium	ppm	<b>43</b>		 
Magnesium	ppm	■8		 
Zinc	ppm	■37		 
Phosphorus	ppm	<b>1182</b>		 
Barium	ppm	<b>2</b>		 
Boron	ppm	<b>■</b> 68		 



# RIPA AND ASSOCIATES 10149 FISHER AVENUE TAMPA, FL US 33619 Contact: ROBERT TURNER rturner@ripatampa.com T:

#### Diagnosis

F:

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Confirm oil type. The condition of the oil is acceptable for the time in service.

Depot:RIPTAMUnique No:8974728Signed:Don BaldridgeReport Date:31 Mar 2020



### **CONSTRUCTION EQUIPMENT**





