



CONSTRUCTION EQUIPMENT

ASCENDUM MACHINERY 44145 PEDULLA

VOLVO A30G ORT-23 (S/N A30GV742351) REAR LEFT FINAL



Sample No: VCP286189
Oil Type: {unknown}
Job No: 44145 PEDULLA



SAMPLE INFORMATION

Sample Number	VCP286189	---	---	---
Sample Date	07 Dec 2020	---	---	---
Machine Hours	568	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

PEDULLA EXCAVATING & PAVING
1275 SHINN FARM RD
MOORESVILLE, NC
US 28115
Contact: Service Manager



OIL CONDITION

Visc @ 40°C	cSt	62.0	---	---	---
-------------	-----	------	-----	-----	-----

T:
F:



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	0	---	---	---
Sodium	ppm	5	---	---	---
Potassium	ppm	14	---	---	---

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	169	---	---	---
Copper	ppm	12	---	---	---
Lead	ppm	0	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	<1	---	---	---
Chromium	ppm	4	---	---	---
Molybdenum	ppm	2	---	---	---
Nickel	ppm	2	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	10	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	105	---	---	---
Magnesium	ppm	2	---	---	---
Zinc	ppm	37	---	---	---
Phosphorus	ppm	1297	---	---	---
Barium	ppm	<1	---	---	---
Boron	ppm	180	---	---	---

Depot: PEDMOOVC
Unique No: 9285626
Signed: Don Baldrige
Report Date: 14 Dec 2020



CONSTRUCTION EQUIPMENT



GRAPHS

