



# CONSTRUCTION EQUIPMENT

ASCENDUM MACHINERY 44145 PEDULLA VOLVO A30G ORT-23 (S/N A30GV742551) - BOGIE/CENTER RIGHT FINAL



**Sample No:** VCP290102  
**Oil Type:** {unknown}  
**Job No:** 44145 PEDULLA



## SAMPLE INFORMATION

Sample Number	VCP290102	---	---	---
Sample Date	07 Dec 2020	---	---	---
Machine Hours	568	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

**PEDULLA EXCAVATING & PAVING**  
1275 SHINN FARM RD  
MOORESVILLE, NC  
US 28115  
Contact: Service Manager



## OIL CONDITION

Visc @ 40°C	cSt	█ 61.9	---	---	---
-------------	-----	--------	-----	-----	-----

T:  
F:



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 0	---	---	---
Sodium	ppm	█ 5	---	---	---
Potassium	ppm	█ 0	---	---	---

## Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



## WEAR METALS

Iron	ppm	█ 129	---	---	---
Copper	ppm	█ 7	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 3	---	---	---
Molybdenum	ppm	4	---	---	---
Nickel	ppm	█ 1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	10	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	111	---	---	---
Magnesium	ppm	<1	---	---	---
Zinc	ppm	43	---	---	---
Phosphorus	ppm	1274	---	---	---
Barium	ppm	<1	---	---	---
Boron	ppm	182	---	---	---

**Depot:** PEDMOOVC  
**Unique No:** 9285642  
**Signed:** Don Baldrige  
**Report Date:** 14 Dec 2020



# CONSTRUCTION EQUIPMENT



## GRAPHS

