



CONSTRUCTION EQUIPMENT

ASCENDUM MACHINERY 44145 PEDULLA

VOLVO A30G ORT-23 (S/N A30GV742551) - FRONT LEFT FINAL



Sample No: VCP295779
Oil Type: {unknown}
Job No: 44145 PEDULLA



SAMPLE INFORMATION

Sample Number	VCP295779	---	---	---
Sample Date	07 Dec 2020	---	---	---
Machine Hours	568	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

PEDULLA EXCAVATING & PAVING
1275 SHINN FARM RD
MOORESVILLE, NC
US 28115
Contact: Service Manager



OIL CONDITION

Visc @ 40°C	cSt	62.0	---	---	---
-------------	-----	------	-----	-----	-----

T:
F:



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	0	---	---	---
Sodium	ppm	4	---	---	---
Potassium	ppm	0	---	---	---

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	141	---	---	---
Copper	ppm	11	---	---	---
Lead	ppm	0	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	<1	---	---	---
Chromium	ppm	3	---	---	---
Molybdenum	ppm	2	---	---	---
Nickel	ppm	2	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	11	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	121	---	---	---
Magnesium	ppm	0	---	---	---
Zinc	ppm	44	---	---	---
Phosphorus	ppm	1258	---	---	---
Barium	ppm	<1	---	---	---
Boron	ppm	180	---	---	---

Depot: PEDMOOVC
Unique No: 9285643
Signed: Don Baldrige
Report Date: 14 Dec 2020



CONSTRUCTION EQUIPMENT



GRAPHS

