



CONSTRUCTION EQUIPMENT

615073 VOLVO A40G 342110 - COOLANT



Sample No: VCP300327
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: 615073



SAMPLE INFORMATION

Sample Number	VCP300327	VCP279829	VCP262299	VCP244508
Sample Date	11 Jan 2021	29 Jul 2020	12 Dec 2019	30 Aug 2019
Machine Hours	3210	2406	1661	1019
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL



COOLANT CONDITION

pH	Scale 0-14	7.70	7.53	7.76	8.06
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	0	0	0
Percentage Glycol	%	48	45	44	43
Freezing Point	°C	-32	-27	-25	-23



CONTAMINATION

Coolant Appearance	normal	normal	normal	normal
Coolant Color	Orange	Yllow	Yllow	Yllow

ALTA EQUIPMENT

5985 COURT STREET ROAD
 SYRACUSE, NY
 US 13206
 Contact: JIM STRIGLE
 JIM.STRIGLE@ALTG.COM
 T: (315)437-2611
 F: (315)434-9471

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: VOLVO0142
Unique No: 9325881
Signed: Jonathan Hester
Report Date: 20 Jan 2021



CONSTRUCTION EQUIPMENT




VOLVO GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

