

Sample No: VCP305337
Oil Type: NOT GIVEN

Job No: SWO-571169-20

SAMPL	E INFORMATION			
Sample Number	•	VCP305337	 	
Sample Date		10 Mar 2021	 	
Machine Hours		3651	 	
Sample Status		NORMAL	 	
FUEL CO	ONDITION			
Sulfur	ppm	7	 	
Visc @ 40°C	cSt	■3.09	 	
VOLVO	MINATION			
LUNIA	MINATION			
Water	%	■ 0.002	 	
Lead	ppm	2	 	
Nickel	ppm	0	 	
Aluminum	ppm	■ <1	 	
Vanadium	ppm	0	 	
Silicon	ppm		 	



MAPLE RIDGE HARDWOODS

2270 N DOBLER RD STERLING, MI US 48659 Contact: STEVE BENDER mapleridge.shop@aol.com T: (989)873-8185 F:

Diagnosis

This is a baseline read-out on the submitted sample. All metal levels are normal indicating no corrosion in the cooling system. The water content is negligible. There is no indication of any contamination in the fuel.

Depot:MAPSTEUnique No:9406441Signed:Jonathan HesterReport Date:19 Mar 2021



CONSTRUCTION EQUIPMENT





