



# CONSTRUCTION EQUIPMENT

W215226 VOLVO L60H 621480 - REAR AXLE



**Sample No:** VCP303774  
**Oil Type:** VOLVO WB 102  
**Job No:** W215226



## SAMPLE INFORMATION

Sample Number	<b>VCP303774</b>	VCP258243	VCP212148	---
Sample Date	<b>15 Apr 2021</b>	30 Oct 2019	14 Dec 2018	---
Machine Hours	<b>2934</b>	1992	1031	---
Oil Hours	<b>2900</b>	1992	1000	---
Oil Changed	<b>Not Chngd</b>	Changed	N/A	---
Sample Status	<b>NORMAL</b>	ABNORMAL	NORMAL	---

**ULSTER COUNTY RESOURCE RECOVERY AGENCY**  
 999 FLATBUSH AVE  
 KINGSTON, NY  
 US 12401  
 Contact: CHARLES WHITTAKER  
 cwhf@ucrra.net  
 T: (845)399-2686  
 F:



## OIL CONDITION

Visc @ 40°C	cSt	<b>40.5</b>	40.3	40.34	---
-------------	-----	-------------	------	-------	-----



## CONTAMINATION

Water	%	<b>NEG</b>	NEG	NEG	---
Silicon	ppm	<b>13</b>	9	14	---
Sodium	ppm	<b>5</b>	3	2	---
Potassium	ppm	<b>0</b>	<1	2	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



## WEAR METALS

Iron	ppm	<b>39</b>	101	130	---
Copper	ppm	<b>&lt;1</b>	▲ 152	1	---
Lead	ppm	<b>&lt;1</b>	2	0	---
Tin	ppm	<b>&lt;1</b>	4	0	---
Aluminum	ppm	<b>1</b>	<1	<1	---
Chromium	ppm	<b>1</b>	2	5	---
Molybdenum	ppm	<b>&lt;1</b>	2	2	---
Nickel	ppm	<b>&lt;1</b>	1	<1	---
Titanium	ppm	<b>&lt;1</b>	0	1	---
Silver	ppm	<b>&lt;1</b>	0	0	---
Manganese	ppm	<b>2</b>	4	8	---
Vanadium	ppm	<b>&lt;1</b>	0	0	---



## ADDITIVES

Calcium	ppm	<b>4273</b>	4072	4144	---
Magnesium	ppm	<b>14</b>	7	9	---
Zinc	ppm	<b>1636</b>	1578	1653	---
Phosphorus	ppm	<b>1341</b>	1308	1246	---
Barium	ppm	<b>0</b>	0	0	---
Boron	ppm	<b>139</b>	119	117	---

**Depot:** ULSKIN  
**Unique No:** 9514968  
**Signed:** Wes Davis  
**Report Date:** 24 May 2021



# CONSTRUCTION EQUIPMENT



## GRAPHS

