

# CONSTRUCTION EQUIPMENT SW0069767 WASTE CON VOLVO L90H 624438 - COOLANT

Sample No: VCP314717

Oil Type: **VOLVO COOLANT VCS (YELLOW)** 

Job No: SWO069767 WASTE CON

| SAMPLE II          | NFORMATION |             |  |  |  |
|--------------------|------------|-------------|--|--|--|
| Sample Number      | -          | VCP314717   |  |  |  |
| Sample Date        |            | 25 May 2021 |  |  |  |
| Machine Hours      |            | 3926        |  |  |  |
| Sample Status      |            | NORMAL      |  |  |  |
|                    |            |             |  |  |  |
| COOLANT CONDITION  |            |             |  |  |  |
| рН                 | Scale 0-14 | <b>7.75</b> |  |  |  |
| Reserve Alkalinity | Scale 0-20 |             |  |  |  |
| Nitrites           | ppm        | ■ NT        |  |  |  |
| Percentage Glycol  | %          | <b>49</b>   |  |  |  |
| Freezing Point     | °C         | <b>-37</b>  |  |  |  |
|                    |            |             |  |  |  |
| CONTAMIN           | NATION     |             |  |  |  |
| Coolant Appearance |            | normal      |  |  |  |
| Coolant Color      |            | Green       |  |  |  |



#### ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC

9601 BOGGY CREEK RD ORLANDO, FL US 32824 Contact: Robert LaPlante robert.laplante@altg.com T: (407)508-9736 F: (407)659-8720

### Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: VOLVO0096 **Unique No:** 9529892 Signed: Jonathan Hester Report Date: 08 Jun 2021

Contact/Location: Robert LaPlante - VOLVO0096



## **CONSTRUCTION EQUIPMENT**





