



CONSTRUCTION EQUIPMENT

68706 VOLVO L110H 631235 - COOLANT



Sample No: VCP313183
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: 68706



SAMPLE INFORMATION

Sample Number	VCP313183	---	---	---
Sample Date	07 May 2021	---	---	---
Machine Hours	6168	---	---	---
Sample Status	NORMAL	---	---	---

RIPA AND ASSOCIATES

10149 FISHER AVENUE
 TAMPA, FL
 US 33619

Contact: ROBERT TURNER
 rturner@ripatampa.com

T:
 F:



COOLANT CONDITION

pH	Scale 0-14	■ 7.48	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 0	---	---	---
Percentage Glycol	%	■ 50	---	---	---
Freezing Point	°C	■ -39	---	---	---

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Red	---	---	---

Depot: RIPTAM
Unique No: 9555017
Signed: Doug Bogart
Report Date: 28 Jun 2021



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

