



CONSTRUCTION EQUIPMENT

646398 SENNEBOGEN 840E 840.O.2195 - COOLANT



Sample No: VCP299327
Oil Type: HYBRID (HOAT) COOLANT
Job No: 646398



SAMPLE INFORMATION

Sample Number	VCP299327	---	---	---
Sample Date	14 Jul 2021	---	---	---
Machine Hours	4095	---	---	---
Sample Status	NORMAL	---	---	---

ALTA CONSTRUCTION EQUIPMENT
613 E STEVENSON RD
OTTAWA, IL
US 61350
Contact: KEVIN SKRTICH
KEVIN.SKRTICH@ALTAEQUIPMENT.COM
T:
F:



COOLANT CONDITION

pH	Scale 0-14	■ 7.87	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 52	---	---	---
Freezing Point	°C	■ -44	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: VOLVO5055
Unique No: 9670040
Signed: Jonathan Hester
Report Date: 23 Sep 2021



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

