



# CONSTRUCTION EQUIPMENT

222635 VOLVO L120H 632093 - COOLANT



**Sample No:** VCP256091  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** 222635



## SAMPLE INFORMATION

Sample Number	VCP256091	---	---	---
Sample Date	22 Sep 2021	---	---	---
Machine Hours	13474	---	---	---
Sample Status	NORMAL	---	---	---

**PACWEST MACHINERY**  
 8207 SOUTH 216TH STREET  
 KENT, WA  
 US 98032  
 Contact: CHRIS COPELAND  
 ccopeland@pacwestmachinery.com  
 T: (800)935-5933  
 F: (509)534-5286



## COOLANT CONDITION

pH	Scale 0-14	■ 7.99	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 51	---	---	---
Freezing Point	°C	■ -39	---	---	---

## Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

**Depot:** VOLVO1271  
**Unique No:** 9724519  
**Signed:** Jonathan Hester  
**Report Date:** 05 Nov 2021



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity




### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

