



CONSTRUCTION EQUIPMENT

VOLVO L220G 12011 - COOLANT



Sample No: VCP331137
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No:



SAMPLE INFORMATION

Sample Number	VCP331137	VCP162139	VCE195438	VCP172641
Sample Date	30 Nov 2021	30 Sep 2015	21 Jul 2015	02 May 2015
Machine Hours	18873	12011	8604	8009
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

CALLANAN
 RT 32 677 FLATBUSH RD
 EAST KINGSTON, NY
 US 12401
 Contact:



COOLANT CONDITION

pH	Scale 0-14	8.44	7.40	7.60	7.70
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	0	0	0	0
Percentage Glycol	%	51	52	52	52
Freezing Point	°C	-41	-34	-33	-33

T:
F:



CONTAMINATION

Coolant Appearance	normal	normal	normal	normal
Coolant Color	Yllow	Yllow	Yllow	Yllow

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: CALEAS
Unique No: 9762887
Signed: Doug Bogart
Report Date: 07 Dec 2021




CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

