

Sample No: VCP332006

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: 332144

CVMDIE	INFORMATION				
	INFUNMATION	<u> </u>			
Sample Number		VCP332006	VCP301391	VCP264115	
Sample Date		30 Nov 2021	18 Jan 2021	09 Mar 2020	
Machine Hours		4650	3328	2324	
Oil Hours		100	1000	1000	
Oil Changed		Changed	Changed	Changed	
Sample Status		NORMAL	NORMAL	ATTENTION	
OIL COND	NITION				
Visc @ 40°C	cSt	258	□ 239	<u> </u>	
	CSL	230	2 39	155	
VOLVO					
CONTAM	INATION				
Water	%	NEG	NEG	NEG	
Silicon	ppm	4	5	9	
Sodium	ppm	2	<u></u> 2	<u></u>	
Potassium	ppm	O	7	_ 1	
		_			
VOLVO	FTALC				
WEAR M	FIAL2				
Iron	ppm	60	■88	241	
Copper	ppm	■<1	- <1	<u> </u>	
Lead	ppm	0	0	0	
Tin	ppm	■0	0	□0	
Aluminum	ppm	■<1	< 1	- < 1	
Chromium	ppm	■<1	- <1	2	
Molybdenum	ppm	2	1	0	
Nickel	ppm	0	0	<1	
Titanium	ppm	0	0	<1	
Silver	ppm	2	0	0	
Manganese	ppm	2	2	■8	
Vanadium	ppm	0	0	0	
ADDITIV	77				
	-				
Calcium	ppm	■34	□ 56	6 1	
Magnesium	ppm	■9	5	9	
Zinc	ppm	44	39	■ 53	
Phosphorus	ppm	■843	953	1166	
Barium	ppm	□ 0	1	4	
Boron	ppm	96	■81	101	



RIPA AND ASSOCIATES 10149 FISHER AVENUE TAMPA, FL US 33619 Contact: ROBERT TURNER rturner@ripatampa.com T:

Diagnosis

F:

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:RIPTAMUnique No:9802564Signed:Don BaldridgeReport Date:07 Jan 2022



CONSTRUCTION EQUIPMENT





GRAPHS

