



CONSTRUCTION EQUIPMENT

VOLVO A40F 11510 - COOLANT



Sample No: VCP341031
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No:



SAMPLE INFORMATION

Sample Number	VCP341031	VCP147726	---	---
Sample Date	01 Feb 2022	08 May 2019	---	---
Machine Hours	12725	8125	---	---
Sample Status	NORMAL	ABNORMAL	---	---



COOLANT CONDITION

pH	Scale 0-14	7.82	7.28	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	0	---	---
Percentage Glycol	%	63	74	---	---
Freezing Point	°C	-75	-85	---	---



CONTAMINATION

Coolant Appearance	normal	normal	---	---
Coolant Color	Yllow	Yllow	---	---

ALTA EQUIPMENT

5985 COURT STREET ROAD
 SYRACUSE, NY
 US 13206
 Contact: JIM STRIGLE
 JIM.STRIGLE@ALTG.COM
 T: (315)437-2611
 F: (315)434-9471

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: VOLVO0142
Unique No: 9841087
Signed: Jonathan Hester
Report Date: 09 Feb 2022



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

