



# CONSTRUCTION EQUIPMENT

SPM366789 FH PASCHEN VOLVO L90H 625532 - REAR AXLE



**Sample No:** VCP334832  
**Oil Type:** VOLVO WET BRAKE TRANSAXLE OIL  
**Job No:** SPM366789 FH PASCHEN



## SAMPLE INFORMATION

Sample Number	VCP334832	---	---	---
Sample Date	08 Feb 2022	---	---	---
Machine Hours	2699	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Changed	---	---	---
Sample Status	NORMAL	---	---	---

**FH PASCHEN**  
5515 N EAST RIVER RD  
CHICAGO, IL  
US 60631  
Contact: MARC PATLA  
mpatla@fhpaschen.com  
T: (224)297-9398  
F:



## OIL CONDITION

Visc @ 40°C	cSt	■ 39.9	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	■ 15	---	---	---
Sodium	ppm	■ 11	---	---	---
Potassium	ppm	■ <1	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



## WEAR METALS

Iron	ppm	■ 139	---	---	---
Copper	ppm	■ 54	---	---	---
Lead	ppm	■ 1	---	---	---
Tin	ppm	■ 7	---	---	---
Aluminum	ppm	■ 2	---	---	---
Chromium	ppm	■ 5	---	---	---
Molybdenum	ppm	■ 6	---	---	---
Nickel	ppm	■ 1	---	---	---
Titanium	ppm	■ 0	---	---	---
Silver	ppm	■ 0	---	---	---
Manganese	ppm	■ 14	---	---	---
Vanadium	ppm	■ <1	---	---	---



## ADDITIVES

Calcium	ppm	■ 4407	---	---	---
Magnesium	ppm	■ 16	---	---	---
Zinc	ppm	■ 1694	---	---	---
Phosphorus	ppm	■ 1453	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 127	---	---	---

**Depot:** FHPCHIL  
**Unique No:** 9855008  
**Signed:** Wes Davis  
**Report Date:** 17 Feb 2022



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

