



# CONSTRUCTION EQUIPMENT

813638 VOLVO ECR235EL 310702 - COOLANT



**Sample No:** VCP350051  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** 813638



## SAMPLE INFORMATION

Sample Number	<b>VCP350051</b>	VCP336217	---	---
Sample Date	<b>02 Mar 2022</b>	20 Sep 2021	---	---
Machine Hours	<b>3512</b>	3476	---	---
Sample Status	<b>NORMAL</b>	ABNORMAL	---	---

**ALTA EQUIPMENT CO - ORLAND PARK**  
 5000 INDUSTRIAL HWY  
 GARY, IN  
 US 46406  
 Contact: DAVE ENG  
 DAVE.ENG@ALTG.COM  
 T: (312)350-2560  
 F:



## COOLANT CONDITION

pH	Scale 0-14	<b>8.04</b>	7.65	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	<b>0</b>	NT	---	---
Percentage Glycol	%	<b>46</b>	45	---	---
Freezing Point	°C	<b>-29</b>	-25	---	---

## Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	<b>normal</b>	▲ oil	---	---
Coolant Color	<b>Yllow</b>	Yllow	---	---

**Depot:** VOLVO8885  
**Unique No:** 9878554  
**Signed:** Doug Bogart  
**Report Date:** 08 Mar 2022




# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity




### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

