



# CONSTRUCTION EQUIPMENT

W127867 VOLVO EC250EL 314145 - COOLANT



**Sample No:** VCP359468  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** W127867



## SAMPLE INFORMATION

Sample Number	VCP359468	---	---	---
Sample Date	06 Apr 2022	---	---	---
Machine Hours	1122	---	---	---
Sample Status	NORMAL	---	---	---



## COOLANT CONDITION

pH	Scale 0-14	■ 8.05	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 0	---	---	---
Percentage Glycol	%	■ 52.5	---	---	---
Freezing Point	°C	■ -40	---	---	---



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

### ALTA EQUIPMENT

5985 COURT STREET ROAD  
 SYRACUSE, NY  
 US 13206

Contact: JIM STRIGLE  
 JIM.STRIGLE@ALTG.COM  
 T: (315)437-2611  
 F: (315)434-9471

### Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

**Depot:** VOLVO0142  
**Unique No:** 9930680  
**Signed:** Doug Bogart  
**Report Date:** 13 Apr 2022



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity




### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

