



CONSTRUCTION EQUIPMENT

W127935 VOLVO A30G 752462 - COOLANT



Sample No: VCP355686
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: W127935



SAMPLE INFORMATION

Sample Number	VCP355686	---	---	---
Sample Date	13 Apr 2022	---	---	---
Machine Hours	488	---	---	---
Sample Status	NORMAL	---	---	---



COOLANT CONDITION

pH	Scale 0-14	■ 8.13	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 50.4	---	---	---
Freezing Point	°C	■ -35	---	---	---



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

ALTA EQUIPMENT

5985 COURT STREET ROAD
 SYRACUSE, NY
 US 13206
 Contact: JIM STRIGLE
 JIM.STRIGLE@ALTG.COM
 T: (315)437-2611
 F: (315)434-9471

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: VOLVO0142
Unique No: 9942107
Signed: Doug Bogart
Report Date: 19 Apr 2022




CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

