



CONSTRUCTION EQUIPMENT

RECYCLE AMERICA VOLVO L60H 622532 - COOLANT



Sample No: VCP364336
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: RECYCLE AMERICA



SAMPLE INFORMATION

Sample Number	VCP364336	---	---	---
Sample Date	30 Aug 2022	---	---	---
Machine Hours	5793	---	---	---
Sample Status	NORMAL	---	---	---

WASTE MANAGEMENT TAMPA TRANSFER
 3518 4TH AVE
 TAMPA, FL
 US 33605
 Contact: JOHN POLLOCK
 jpollock2@wm.com
 T: (813)247-7397
 F: (813)247-4847



COOLANT CONDITION

pH	Scale 0-14	■ 7.18	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 0	---	---	---
Percentage Glycol	%	■ 45.4	---	---	---
Freezing Point	°C	■ -24	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: WASTAM
Unique No: 10144144
Signed: Doug Bogart
Report Date: 29 Sep 2022



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

