



# CONSTRUCTION EQUIPMENT

SW1008724 YAVAPI VOLVO L70H 623687 - COOLANT



**Sample No:** VCP353726  
**Oil Type:** VOLVO COOLANT (GREEN)  
**Job No:** SW1008724 YAVAPI



## SAMPLE INFORMATION

Sample Number	VCP353726	---	---	---
Sample Date	16 Sep 2022	---	---	---
Machine Hours	7501	---	---	---
Sample Status	NORMAL	---	---	---

**ARNOLD MACHINERY COMPANY**  
4323 EAST WINSLOW AVENUE  
PHOENIX, AZ  
US 85040  
Contact: RANDY PRZEKURAT  
randyp@arnoldmachinery.com  
T:  
F: (602)414-1904



## COOLANT CONDITION

pH	Scale 0-14	■ 8.26	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 1012	---	---	---
Percentage Glycol	%	■ 57.0	---	---	---
Freezing Point	°C	■ -52	---	---	---

## Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. Glycol and nitrite levels are acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Orange	---	---	---

**Depot:** VOLVO6174  
**Unique No:** 10151581  
**Signed:** Jonathan Hester  
**Report Date:** 30 Sep 2022



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity




### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

