### CONSTRUCTION EQUIPMENT SWA073441 VOLVO EC480EL 310354 - COOLANT




 Sample No:
 VCP384779

 Oil Type:
 VOLVO COOLANT VCS (YELLOW)

 Job No:
 SWA073441

VOLVO

#### SAMPLE INFORMATION VCP384779 Sample Number VCP314277 Sample Date 29 Sep 2022 04 May 2021 Machine Hours 6700 4933 Sample Status NORMAL NORMAL **COOLANT CONDITION** Scale 0-14 pН 7.45 7.31 Reserve Alkalinity Scale 0-20 ----Nitrites NT ppm 54 Percentage Glycol % 51.9 -48 Freezing Point °C -38 CONTAMINATION





SENECA MEADOWS

1786 SALCMAN ROAD WATERLOO, NY US Contact: EDWARD BARTO ebarto@iesi.com T: (315)539-5624 F: (315)539-4656

### Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:SENWATUnique No:10164745Signed:Jonathan HesterReport Date:11 Oct 2022


## **CONSTRUCTION EQUIPMENT**



# GRAPHS

#### Iron/Tin/Silver

VOLVO



Report Id: SENWAT [WUSCAR] 05660176 (Generated: 11/17/2023 09:49:58) Rev: 1

Contact/Location: EDWARD BARTO - SENWAT