



CONSTRUCTION EQUIPMENT

465316 TUCKER PAVING - COOLANT



Sample No: VCP390706
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: 465316 TUCKER PAVING



SAMPLE INFORMATION

Sample Number	VCP390706	---	---	---
Sample Date	12 Oct 2022	---	---	---
Machine Hours	6141	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
 8418 PALM RIVER ROAD
 TAMPA, FL
 US 33619
 Contact: KENNY HANEY
 khaney@flaglerce.com
 T: (813)630-0077
 F: (813)630-2233



COOLANT CONDITION

pH	Scale 0-14	■ 7.41	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 51.5	---	---	---
Freezing Point	°C	■ -38	---	---	---

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Orange	---	---	---

Depot: VOLVO0093
Unique No: 10241309
Signed: Jonathan Hester
Report Date: 05 Dec 2022



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

