



CONSTRUCTION EQUIPMENT

SWA142888 VOLVO L110H 10425 - COOLANT



Sample No: VCP368737
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: SWA142888



SAMPLE INFORMATION

| | | | | |
|---------------|--------------------|-------------|-------------|-------------|
| Sample Number | VCP368737 | VCP326422 | VCP305295 | VCP244795 |
| Sample Date | 06 Jan 2023 | 08 Oct 2021 | 11 Mar 2021 | 30 Oct 2020 |
| Machine Hours | 9253 | 8490 | 7265 | 6382 |
| Sample Status | NORMAL | NORMAL | NORMAL | NORMAL |

ALTA EQUIPMENT

5985 COURT STREET ROAD
 SYRACUSE, NY
 US 13206

Contact: JIM STRIGLE
 JIM.STRIGLE@ALTG.COM
 T: (315)437-2611
 F: (315)434-9471



COOLANT CONDITION

| | | | | | |
|--------------------|------------|-------------|------|------|------|
| pH | Scale 0-14 | 7.60 | 7.53 | 7.48 | 7.39 |
| Reserve Alkalinity | Scale 0-20 | --- | --- | --- | --- |
| Nitrites | ppm | NT | NT | 0 | NT |
| Percentage Glycol | % | 46.8 | 46 | 48 | 51 |
| Freezing Point | °C | -26 | -29 | -34 | -41 |

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

| | | | | |
|--------------------|---------------|--------|--------|--------|
| Coolant Appearance | normal | normal | normal | normal |
| Coolant Color | Orange | Orange | Green | Yellow |

Depot: VOLVO0142
Unique No: 10287143
Signed: Doug Bogart
Report Date: 14 Jan 2023




CONSTRUCTION EQUIPMENT




VOLVO GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

