

## CONSTRUCTION EQUIPMENT X42315 VOLVO A25G 742373 - WET DISC BRAKE



Sample No: VCP371093
Oil Type: VOLVO WB 102

**Job No:** X42315

SAMPLE	INFORMATION			
Sample Number		VCP371093	 	
Sample Date		23 Jan 2023	 	
Machine Hours		2932	 	
Oil Hours		2932	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
Sample Status		ADITORIVIAL		
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	■38.5	 	
		_		
VOLVO	AIN A TION			
LUNIAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	<b>19</b>	 	
Sodium	ppm	<b>7</b>	 	
Potassium	ppm	<b>2</b>	 	
WEAR N	AETAL C			
	JE I ML7			
Iron	ppm	■24	 	
Copper	ppm	<u></u> 425	 	
Lead	ppm	<b></b>	 	
Tin	ppm	<b>■&lt;1</b>	 	
Aluminum	ppm	<b>■</b> 2	 	
Chromium	ppm	<b>■&lt;1</b>	 	
Molybdenum	ppm	<b>■&lt;1</b>	 	
Nickel	ppm	<b>■&lt;1</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>2</b>	 	
Vanadium	ppm	0	 	
ADDITIV	/ES			
Calcium	ppm	3162	 	
Magnesium	ppm	■ 7	 	
Zinc	ppm	1298	 	
Phosphorus		1151	 	
Barium	ppm	<b>0</b>	 	
	ppm			
Boron	ppm	<b>104</b>	 	



SCOTT EQUIPMENT COMPANY LLC - Lavergne
1231 BRIDGESTONE PARKWAY
LAVERGNE, TN
US 37086
Contact: CLAY COULTER
CCOULTER@SCOTTCOMPANIES.COM
T: (615)793-3888
F: (615)793-9655

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VOLVO0129

 Unique No:
 10310738

 Signed:
 Don Baldridge

 Report Date:
 29 Jan 2023



## **CONSTRUCTION EQUIPMENT**





