

Sample No: VCP402254

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: 2194BO

SAMPLE INFORMATION					
Sample Number		VCP402254	VCP336374	VCP301423	VCP292064
Sample Date		25 Jan 2023	28 Sep 2021	02 Mar 2021	30 Nov 2020
Machine Hours		6038	4058	2937	2553
Oil Hours		0	0	0	0
Oil Changed		Changed	Changed	Not Changd	Not Changd
Sample Status		SEVERE	SEVERE	SEVERE	SEVERE
OIL CONDITION					
Visc @ 40°C	cSt	■308	214	234	232
VOLVO					
CONTAMINATION					
Water	%	<u> </u>			
Silicon	ppm	1450	357	663	440
Sodium	ppm	16	5	■9	■5
Potassium	ppm	150	■40	□ 64	6
VOLVO					
WEAR ME	TALS				
Iron	ppm	3502	<u>▲</u> 1229	2563	2227
Copper	ppm	■8	2	6	5
Lead	ppm	1	□0	2	0
Tin	ppm	■<1	□0	□0	□0
Aluminum	ppm	<u> </u>	▲ 103	<u>194</u>	<u>120</u>
Chromium	ppm	<u> </u>	1 1	2 5	<u>^</u> 21
Molybdenum	ppm	■ 6	2	0	0
Nickel	ppm	2	2	2	<1
Titanium	ppm	<u>^</u> 22	7	1 3	8
Silver	ppm	■0	0	0	<1
Manganese	ppm	■21	7	■18	1 6
Vanadium	ppm	1	<1	0	<1
VOLVO					
ADDITIVE	5				
Calcium	ppm	■363	224	■181	1 40
Magnesium	ppm	141	□72	4 3	□31
Zinc	ppm	■73	■124	■108	□ 107
Phosphorus	ppm	■853	■838	□751	753
Barium	ppm	1	- <1	0	- <1
Boron	ppm	158	■133	6 5	68



CHARTER HOMES

1190 DILLERVILLE RD LANCASTER, PA US 17601 Contact: NEIL CLARK

T: (717)564-3031 F:

Diagnosis

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Gear wear is indicated. There is a light concentration of water present in the oil. Elemental levels of silicon (Si) and aluminum (Al) indicate aluminasilicate (coarse dirt) ingress. The oil is no longer serviceable due to the presence of contaminants.

Depot:CHALANPAUnique No:10319883Signed:Don BaldridgeReport Date:01 Feb 2023



CONSTRUCTION EQUIPMENT





