



CONSTRUCTION EQUIPMENT

SWA120029-10 VOLVO L110H 631934 - COOLANT



Sample No: VCP390555
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: SWA120029-10



SAMPLE INFORMATION

Sample Number	VCP390555	---	---	---
Sample Date	22 Dec 2022	---	---	---
Machine Hours	1075	---	---	---
Sample Status	NORMAL	---	---	---



COOLANT CONDITION

pH	Scale 0-14	■ 7.78	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 50.4	---	---	---
Freezing Point	°C	■ -35	---	---	---



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---



ULSTER COUNTY RESOURCE RECOVERY AGENCY
 999 FLATBUSH AVE
 KINGSTON, NY
 US 12401
 Contact: CHARLES WHITTAKER
 cwhf@ucrra.net
 T: (845)399-2686
 F:

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: ULSKIN
Unique No: 10332310
Signed: Jonathan Hester
Report Date: 10 Feb 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

