



CONSTRUCTION EQUIPMENT

SPM502739 OMNISOURCE SENNEBOGEN 825 825.0.2100 - REAR AXLE



Sample No: VCP379812
Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5
Job No: SPM502739 OMNISOURCE



SAMPLE INFORMATION

Sample Number	VCP379812	VCP290820	VCP256341	---
Sample Date	10 Feb 2023	07 Dec 2020	09 Jan 2020	---
Machine Hours	8011	5907	5012	---
Oil Hours	0	0	0	---
Oil Changed	Changed	Changed	Changed	---
Sample Status	NORMAL	NORMAL	NORMAL	---

ALTA CONSTRUCTION EQUIPMENT LLC
 G-3283 S. DORT HIGHWAY
 BURTON, MI
 US 48529
 Contact: BURTON SERVICE
 BURTON.SERVICE@ALTAEQUIPMENT.COM
 T:
 F:



OIL CONDITION

Visc @ 40°C	cSt	146	139	111	---
-------------	-----	------------	-----	-----	-----



CONTAMINATION

Silicon	ppm	3	2	6	---
Sodium	ppm	4	4	8	---
Potassium	ppm	0	<1	<1	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	26	11	29	---
Copper	ppm	<1	1	4	---
Lead	ppm	0	0	0	---
Tin	ppm	0	<1	<1	---
Aluminum	ppm	0	0	<1	---
Chromium	ppm	<1	<1	<1	---
Molybdenum	ppm	0	<1	0	---
Nickel	ppm	<1	<1	<1	---
Titanium	ppm	0	0	0	---
Silver	ppm	0	<1	0	---
Manganese	ppm	<1	<1	2	---
Vanadium	ppm	0	0	0	---



ADDITIVES

Calcium	ppm	43	174	1032	---
Magnesium	ppm	0	1	3	---
Zinc	ppm	21	81	427	---
Phosphorus	ppm	1841	2380	1660	---
Barium	ppm	0	0	1	---
Boron	ppm	168	194	120	---

Depot: VOLVO5023
Unique No: 10344573
Signed: Wes Davis
Report Date: 17 Feb 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

