

CONSTRUCTION EQUIPMENT VOLVO A30G 752233 - WET DISC BRAKE



Sample No: VCP395392
Oil Type: VOLVO WB 102

Job No:

VOLVO				
	INFORMATION			
Sample Number	-	VCP395392	 	
Sample Date		03 Apr 2023	 	
Machine Hours		1100	 	
Oil Hours		1100	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
OIL CONE	DITION			
Visc @ 40°C	cSt	42.2	 	
CONTAM	IINATION			
		į.		
Water	%	NEG	 	
Silicon	ppm	21	 	
Sodium	ppm	7	 	
Potassium	ppm	■ <1	 	
VOLVO				
WEAR M	IETALS			
Iron	ppm	13	 	
Copper	ppm	4 238	 	
Lead	ppm	2	 	
Tin	ppm	■0	 	
Aluminum	ppm	1	 	
Chromium	ppm	■ 0	 	
Molybdenum	ppm	■<1	 	
Nickel	ppm	■0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	1	 	
Vanadium	ppm	0	 	
ADDITIV	ES			
Calcium	ppm	■3377	 	
Magnesium	ppm	15	 	
Zinc	ppm	1279	 	
Phosphorus	ppm	1110	 	
Barium	ppm	0	 	
Boron	ppm	125	 	



ALTA EQUIPMENT

5985 COURT STREET ROAD SYRACUSE, NY US 13206 Contact: JOSH GAVIN

T: (585)344-1931 F: (315)437-8558

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0142Unique No:10416975Signed:Don BaldridgeReport Date:12 Apr 2023



CONSTRUCTION EQUIPMENT





