



CONSTRUCTION EQUIPMENT

VOLVO A30G 752233 - COOLANT



Sample No: VCP382399
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No:



SAMPLE INFORMATION

Sample Number	VCP382399	---	---	---
Sample Date	03 Apr 2023	---	---	---
Machine Hours	1100	---	---	---
Sample Status	NORMAL	---	---	---



COOLANT CONDITION

pH	Scale 0-14	■ 7.70	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 50.5	---	---	---
Freezing Point	°C	■ -35	---	---	---



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

ALTA EQUIPMENT

5985 COURT STREET ROAD
 SYRACUSE, NY
 US 13206
 Contact: JOSH GAVIN

T: (585)344-1931
 F: (315)437-8558

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: VOLVO0142
Unique No: 10417094
Signed: Jonathan Hester
Report Date: 12 Apr 2023



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

