

## CONSTRUCTION EQUIPMENT 218645 ALTA RENTS VOLVO EC480 311142 - DIESEL ENGINE

Sample No: VCP406886

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No: 218645 ALTA RENTS

SAMPLE II	NFORMATION			
Sample Number	-	VCP406886	 	
Sample Date		19 Apr 2023	 	
Machine Hours		5432	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
OIL CONDI	TION			
Visc @ 100°C	cSt	<u> </u>	 	
Base Number (BN)	mg KOH/g	■8.0	 	
Oxidation (PA)	%	78	 	
CONTAMI	NATION			
Soot %	%	■ 0.2	 	
Nitration (PA)	%	64	 	

LUNTAMINATION						
Soot %	%	■ 0.2				
Nitration (PA)	%	64				
Sulfation (PA)	%	55				
Glycol	%	NEG				
Fuel	%	<b>2.2</b>				
Silicon	ppm	<b>■</b> 8				
Sodium	ppm	<b>2</b>				
Potassium	ppm	<b>■</b> 0				

WEAR METALS					
Iron	ppm	<b>10</b>			
Copper	ppm	<b>■</b> 2			
Lead	ppm	<b>0</b>			
Tin	ppm	<b>■&lt;1</b>			
Aluminum	ppm	<b>2</b>			
Chromium	ppm	<b>■&lt;1</b>			
Molybdenum	ppm	<b>42</b>			
Nickel	ppm	<b>■</b> 2			
Titanium	ppm	0			
Silver	ppm	<b>■</b> 0			
Manganese	ppm	<b>■&lt;1</b>			
Vanadium	ppm	0			

ADDITIVES					
Calcium	ppm	<b>1437</b>			
Magnesium	ppm	<b>473</b>			
Zinc	ppm	<b>957</b>			
Phosphorus	ppm	■824			
Barium	ppm	<b>0</b>			
Boron	ppm	■25			



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC 9601 BOGGY CREEK RD ORLANDO, FL US 32824 Contact: Robert LaPlante robert.laplante@altg.com T: (407)508-9736 F: (407)659-8720

## Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. Light fuel dilution occurring. The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The condition of the oil is suitable for further service.

Depot: VOLVO0096 **Unique No:** 10440755 Signed: Wes Davis Report Date: 26 Apr 2023



## **CONSTRUCTION EQUIPMENT**





## GRAPH

