

CONSTRUCTION EQUIPMENT
SPM538832 WHEELER VOLVO L90H 626490 - REAR RIGHT FINAL

Sample No: VCP406921

Oil Type: **VOLVO WET BRAKE TRANSAXLE OIL** 

Job No: SPM538832 WHEELER

VOLVO	INFORMATION	J		
	INFORMATION			_
Sample Number		VCP406921		 
Sample Date		14 Apr 2023		 
Machine Hours		1006		 
Oil Hours		0		 
Oil Changed		Changed		 
Sample Status		NORMAL		 
OIL CONE	NITION			
			<u> </u>	
Visc @ 40°C	cSt	<b>40.9</b>		 
VOLVO				
CONTAM	INATION			
Silicon	ppm	<b>20</b>		 
Sodium	ppm	■11		 
Potassium	ppm	<b>0</b>		 
i otassiaiii	ррпп			
VOLVO				
WEAR M	ETALS			
Iron	ppm	<b>105</b>		 
Copper	ppm	<b>2</b>		 
Lead	ppm	<b>0</b>		 
Tin	ppm	<b>■</b> 0		 
Aluminum	ppm	<b>2</b>		 
Chromium	ppm	<b>■</b> 4		 
Molybdenum	ppm	<b>14</b>		 
Nickel	ppm	<b>■&lt;1</b>		 
Titanium	ppm	<1		 
Silver	ppm	0		 
Manganese	ppm	<b>12</b>		 
Vanadium	ppm	0		 
ADDITIV	FC			
	-	-2700		
Calcium	ppm	■3796		 
Magnesium	ppm	<b>15</b>		 
Zinc	ppm	<b>■</b> 1515		 
Phosphorus	ppm	<b>■1283</b>		 
Barium	ppm	<b>0</b>		 
Boron	ppm	<b>136</b>		 



### ALTA CONSTRUCTION EQUIPMENT LLC

G-3283 S. DORT HIGHWAY BURTON, MI US 48529 Contact: BURTON SERVICE BURTON.SERVICE@ALTAEQUIPMENT.COM

T: F:

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO5023 **Unique No:** 10444999 Signed: Wes Davis Report Date: 28 Apr 2023



# **CONSTRUCTION EQUIPMENT**





