

CONSTRUCTION EQUIPMENT

SPM540006 MIBELLON VOLVO L90G 629029 - DIESEL ENGINE

Sample No: VCP400778

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No: SPM540006 MIBELLON

FORMATION				
	VCP400778			
	21 Apr 2023			
	2496			
	0			
	Changed			
	NORMAL			
INN				
	m 12 2			
	_			
	_			
70	52			
ATION				
%	■0.1			
%	43			
%	45			
%	NEG			
%	<1.0			
ppm	■4			
ppm	2			
ppm	6			
214				
	_			
	_			
	_			
	_			
ppiii	<u> </u>			
	% % % % ppm ppm	VCP400778 21 Apr 2023 2496 0 Changed NORMAL ION cSt	VCP400778 21 Apr 2023 2496 0	VCP400778 21 Apr 2023 2496 0 0 Changed NORMAL NORMAL 100N cSt



ALTA CONSTRUCTION EQUIPMENT LLC

G-3283 S. DORT HIGHWAY BURTON, MI US 48529 Contact: BURTON SERVICE BURTON.SERVICE@ALTAEQUIPMENT.COM T:

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VOLVO5023Unique No:10454993Signed:Sean FeltonReport Date:04 May 2023

ppm

ppm

ppm

ppm

ppm

ppm

1115

■908

1155

950

0

■8

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus



CONSTRUCTION EQUIPMENT





