CONSTRUCTION EQUIPMENT SPM540513 ALTA RENTS VOLVO L 180H 5571 - L 180H - FRONT RIG

Sample No: VCP410468 **Oil Type:**

VOLVO

Job No:

Sample Number Sample Date

Machine Hours

Oil Hours

Oil Changed

Sample Status

Visc @ 40°C

Barium

Boron

VOLVO WET BRAKE TRANSAXLE OIL SPM540513 ALTA RENTS

SAMPLE INFORMATION VCP410468 27 Apr 2023 1033 0 Changed NORMAL T: **OIL CONDITION** F: cSt 40.4 CONTAMINATION ppm 14



ALTA CONSTRUCTION EQUIPMENT LLC

G-3283 S. DORT HIGHWAY BURTON, MI US 48529 Contact: BURTON SERVICE BURTON.SERVICE@ALTAEQUIPMENT.COM

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Silicon	ppm	14	 	
Sodium	ppm	9	 	
Potassium	ppm	1	 	
WEAR I	METALS			
Iron	ppm	84	 	
Copper	ppm	5	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	 <1	 	
Chromium	ppm	3	 	
Molybdenum	ppm	3	 	
Nickel	ppm	 <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	6	 	
Vanadium	ppm	0	 	
ADDITI	VES			
Calcium	ppm	3739	 	
Magnesium	ppm	1 3	 	
Zinc	ppm	1678	 	
Phosphorus	ppm	1345	 	

Depot: VOLVO5023 Unique No: 10455734 Signed: Wes Davis Report Date: 04 May 2023

0

126

ppm


ppm

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO5023 [WUSCAR] 05836931 (Generated: 07/03/2023 12:22:33) Rev: 1

Contact/Location: BURTON SERVICE - VOLVO5023