



# CONSTRUCTION EQUIPMENT

RSO-033963 MIDSOUTH VOLVO EC480EL 315025 - COOLANT



**Sample No:** VCP383072  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** RSO-033963 MIDSOUTH



## SAMPLE INFORMATION

Sample Number	VCP383072	---	---	---
Sample Date	09 May 2023	---	---	---
Machine Hours	526	---	---	---
Sample Status	NORMAL	---	---	---

### MIDSOUTH PAVING INC

750 CLOW RD  
BIRMINGHAM, AL  
US 35217

Contact: CHRIS MCCOY  
chmccoy@apac.com

T: (205)365-3448  
F: (205)808-5431



## COOLANT CONDITION

pH	Scale 0-14	■ 8.22	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 50.0	---	---	---
Freezing Point	°C	■ -35	---	---	---

### Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

**Depot:** APABIR  
**Unique No:** 10470119  
**Signed:** Jonathan Hester  
**Report Date:** 17 May 2023




# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity




### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

