

# CONSTRUCTION EQUIPMENT 18719 VOLVO L90H 624722 - TRANSMISSION (AUTO)



Sample No: VCP400945
Oil Type: MOBIL ATF

**Job No:** 18719

SAMPLE	E INFORMATIO	N		
Sample Number	•	VCP400945	 	
Sample Date		09 May 2023	 	
Machine Hours		3337	 	
Oil Hours		3337	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	<b>28.1</b>	 	
VISC @ 40 C	CSC			
VOLVO				
CONTAN	MOITAMIN			
Silicon	ppm	<b>1</b> 3	 	
Sodium	ppm	<b>■</b> 5	 	
Potassium	ppm	<b>2</b>	 	
WEAR	METALS			
Iron	ppm	<b>132</b>	 	
Copper	ppm	<b>11</b>	 	
Lead	ppm	<b>■</b> 0	 	
Tin	ppm	<b>-</b> <1	 	
Aluminum	ppm	<u></u> 5	 	
Chromium	ppm	<b>■&lt;1</b>	 	
Molybdenum	ppm	 <1	 	
Nickel	ppm	<1	 	
Titanium	ppm	0	 	
Silver	ppm	<b>■</b> 0	 	
Manganese	ppm	■10	 	
Vanadium	ppm	0	 	
VOLVO	IFC			
ADDITIV	VE7			
Calcium	ppm	<b>152</b>	 	
Magnesium	ppm	<b>■</b> 9	 	
Zinc	ppm	<b>73</b>	 	
Phosphorus	ppm	<b>178</b>	 	
Barium	ppm	<b>■&lt;1</b>	 	
Boron	ppm	■37	 	



#### ARNOLD MACHINERY COMPANY

4323 EAST WINSLOW AVENUE PHOENIX, AZ US 85040 Contact: RANDY PRZEKURAT randyp@arnoldmachinery.com T: F: (602)414-1904

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO6174Unique No:10471676Signed:Doug BogartReport Date:17 May 2023



## **CONSTRUCTION EQUIPMENT**





