CONSTRUCTION EQUIPMENT X43639 VOLVO A40F 11840 - REAR AXLE




 Sample No:
 VCP418781

 Oil Type:
 GEAR OIL SAE 80W90

 Job No:
 X43639

VOLVO

SAMPLE INFORMATION VCP418781 Sample Number Sample Date 23 May 2023 Machine Hours 21392 Oil Hours 0 Oil Changed Not Changd ABNORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 110 CONTAMINATION Water % **6** 0.329 Silicon 93 ppm Sodium 1 🔲 ppm Potassium ppm 16 WEAR METALS Iron ppm Copper ppm 6 Lead ppm 0 🔲 Tin ppm 0 Aluminum ppm Chromium **4** ppm Molybdenum ppm 11 Nickel 3 ppm Titanium 3 ppm Silver 0 ppm Manganese ppm 15 Vanadium ppm <1 01 **ADDITIVES**





ROGERS GROUP, INC 421 GREAT CIRCLE ROAD NASHVILLE, TN US 37228 Contact: SERVICE MANAGER

T: (615)780-5730 F:

Diagnosis

No corrective action is recommended at this time. We recommend an early resample to monitor this condition.Gear wear is indicated. There is a light concentration of water present in the oil. The condition of the oil is acceptable for the time in service.


Depot:ROGNASUnique No:10486211Signed:Jonathan HesterReport Date:30 May 2023

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: ROGNAS [WUSCAR] 05856856 (Generated: 09/07/2023 10:02:58) Rev: 1

Contact/Location: SERVICE MANAGER - ROGNAS