



CONSTRUCTION EQUIPMENT

566312 SENNEBOGEN 830 2567 - COOLANT



Sample No: VCP393374
Oil Type: FLEETGUARD ES COMPLEAT
Job No: 566312



SAMPLE INFORMATION

Sample Number	VCP393374	---	---	---
Sample Date	19 Jun 2023	---	---	---
Machine Hours	8895	---	---	---
Sample Status	ABNORMAL	---	---	---

FERROUS PROCESSING AND TRADING

3400 E LAFAYETTE
 DETROIT, MI
 US 48207

Contact: KEITH HALL
 keith.hall@fpt1.com

T:
 F:



COOLANT CONDITION

pH	Scale 0-14	■ 8.06	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 1240	---	---	---
Percentage Glycol	%	■ 62.2	---	---	---
Freezing Point	°C	■ -61	---	---	---

Diagnosis

We recommend drain/flush system, and refill with 50/50 antifreeze water mixture. Sediment present. The pH level of this fluid is within the acceptable limits. Glycol and nitrite levels are acceptable.



CONTAMINATION

Coolant Appearance	▲ sediment	---	---	---
Coolant Color	Black	---	---	---

Depot: FERDET
Unique No: 10526341
Signed: Jonathan Hester
Report Date: 28 Jun 2023



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

