



# CONSTRUCTION EQUIPMENT

554307 APTIM VOLVO A35G 340236 - COOLANT



**Sample No:** VCP424441  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** 554307 APTIM



## SAMPLE INFORMATION

Sample Number	VCP424441	---	---	---
Sample Date	25 May 2023	---	---	---
Machine Hours	6888	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC  
 8418 PALM RIVER ROAD  
 TAMPA, FL  
 US 33619  
 Contact: JOHN FARDELLA  
 john.fardella@altg.com  
 T: (813)630-0077  
 F: (813)630-2233



## COOLANT CONDITION

pH	Scale 0-14	■ 7.23	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 45.7	---	---	---
Freezing Point	°C	■ -24	---	---	---

## Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

**Depot:** VOLVO0093  
**Unique No:** 10526342  
**Signed:** Jonathan Hester  
**Report Date:** 28 Jun 2023



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity




### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

