

CONSTRUCTION EQUIPMENT554566 APTIM VOLVO A35G 340238 - COOLANT



Sample No: VCP424864

Oil Type: VOLVO COOLANT VCS (YELLOW)

Job No: 554566 APTIM

SAMPLE II	NFORMATION				
Sample Number	-	VCP424864			
Sample Date		31 May 2023			
Machine Hours		8953			
Sample Status		NORMAL			
COOLANT CONDITION					
рН	Scale 0-14	7.42			
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	■ NT			
Percentage Glycol	%	47.0			
Freezing Point	°C	-28			
CONTAMIN	NATION				
Coolant Appearance		normal			
Coolant Color		Yllow			



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: JOHN FARDELLA
john.fardella@altg.com
T: (813)630-0077
F: (813)630-2233

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:VOLVO0093Unique No:10526343Signed:Jonathan HesterReport Date:28 Jun 2023



CONSTRUCTION EQUIPMENT





GRAPHS

