

## **CONSTRUCTION EQUIPMENT**

Sample No: VCP345490
Oil Type: NOT GIVEN

**Job No:** \$50600433 HERC

SAMPL	E INFORMATION			
Sample Number		VCP345490	 	
Sample Date		21 Jun 2023	 	
Machine Hours		1355	 	
Sample Status		ABNORMAL	 	
FIIFI (	ONDITION			
Sulfur	ppm	■0	 	
Visc @ 40°C	cSt	<b>2.89</b>	 	
VOLVO				
	MINATION			
Water	%	□0.002	 	
Lead	ppm	<b>0</b>	 	
Nickel	ppm	<b>0</b>	 	
Aluminum	ppm	<b>■</b> 0	 	
Vanadium	ppm	0	 	
Silicon	ppm	<b>-&lt;1</b>	 	



VCES- VOLVO CONSTRUCTION EQUIPMENT
1944 MARINA BLVD
SAN LEANDRO, CA
US 94577
Contact: JOHN BUDESILICH
john.budesilich@vcesvolvo.com
T:
F: (925)294-9240

## Diagnosis

We recommend you service the filters on this component. We advise that you inspect for the source(s) of rust.Light concentration of visible metal present as rust. There is a light amount of visible silt/sediment present in the sample. The water content is negligible. The condition of the fuel appears acceptable for service.

Depot:VOLVO4487Unique No:10533314Signed:Doug BogartReport Date:06 Jul 2023



## **CONSTRUCTION EQUIPMENT**





