



# CONSTRUCTION EQUIPMENT

## 5384-1 VOLVO L90H 625811 - REAR AXLE



**Sample No:** VCP402985  
**Oil Type:** VOLVO WB 102  
**Job No:** 5384-1



### SAMPLE INFORMATION

Sample Number	VCP402985	---	---	---
Sample Date	19 Jun 2023	---	---	---
Machine Hours	840	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

**MCCLUNG-LOGAN EQUIPMENT CO - SALEM**  
 2025 COOK DRIVE  
 SALEM, VA  
 US 24153  
 Contact: SCOTT CARR  
 scarr@mcclung-logan.com  
 T: (540)418-5218  
 F:



### OIL CONDITION

Visc @ 40°C	cSt	█ 40.1	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 13	---	---	---
Sodium	ppm	█ 12	---	---	---
Potassium	ppm	█ 2	---	---	---



### WEAR METALS

Iron	ppm	█ 45	---	---	---
Copper	ppm	█ 22	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 2	---	---	---
Aluminum	ppm	█ 4	---	---	---
Chromium	ppm	█ 3	---	---	---
Molybdenum	ppm	█ 3	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 6	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	█ 3695	---	---	---
Magnesium	ppm	█ 18	---	---	---
Zinc	ppm	█ 1537	---	---	---
Phosphorus	ppm	█ 1218	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 128	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO9010  
**Unique No:** 10534158  
**Signed:** Wes Davis  
**Report Date:** 28 Jun 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

