

## **CONSTRUCTION EQUIPMENT**

SWA289055 DEV CNT FL VOLVO EC350EL 310595 - REAR RIGHT FINAL DRIV

Sample No: VCP425277

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: SWA289055 DEV CNT FL

VOLVO				
ZAMPI F	INFORMATIO	N		
Sample Number	. IIII OIII III	VCP425277	 	
Sample Date		20 Jun 2023	 	
Machine Hours Oil Hours		4895 0		
Oil Changed		Changed		
Sample Status		SEVERE	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	■392	 	
		<del>_</del>		
VOLVO	AINATION			
	MINATION			
Silicon	ppm	<b>426</b>	 	
Sodium	ppm	<b>■</b> 1	 	
Potassium	ppm	<b>4</b>	 	
WEAR M	AFTAI S			
_		4052		
Iron	ppm	1953		
Copper	ppm	<b>■</b> 5	 	
Lead Tin	ppm	8	 	
Aluminum	ppm	□<1 ▲ 54		
	ppm	28	 	
Chromium	ppm	•	 	
Molybdenum	ppm	<b>4</b>	 	
Nickel	ppm			
Titanium	ppm	4	 	
Silver	ppm	0	 	
Manganese	ppm	<b>16</b>	 	
Vanadium	ppm	0	 	
VOLVO				
<b>ADDITIV</b>	/ES			
Calcium	ppm	<b>1</b> 5	 	
Magnesium	ppm	<b>9</b>	 	
Zinc	ppm	<b>■13</b>	 	
Phosphorus	ppm	<b>■733</b>	 	
Barium	ppm	■0	 	
Boron	ppm	■83	 	
	le le			



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
9601 BOGGY CREEK RD
ORLANDO, FL
US 32824
Contact: Robert LaPlante
robert.laplante@altg.com
T: (407)508-9736
F: (407)659-8720

## Diagnosis

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Gear wear is indicated. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. The oil is no longer serviceable due to the presence of contaminants.

Depot:VOLVO0096Unique No:10535182Signed:Jonathan HesterReport Date:30 Jun 2023



## **CONSTRUCTION EQUIPMENT**





