



CONSTRUCTION EQUIPMENT

6574 PINE TIMBER VOLVO L90H 624237 - DIESEL FUEL



Sample No: VCP422908
Oil Type: NOT GIVEN
Job No: 6574 PINE TIMBER



SAMPLE INFORMATION

Sample Number	VCP422908	---	---	---
Sample Date	21 Jun 2023	---	---	---
Machine Hours	12927	---	---	---
Sample Status	SEVERE	---	---	---



FUEL CONDITION

Sulfur	ppm	0	---	---	---
Visc @ 40°C	cSt	2.69	---	---	---



CONTAMINATION

Water	%	0.011	---	---	---
Lead	ppm	0	---	---	---
Nickel	ppm	0	---	---	---
Aluminum	ppm	0	---	---	---
Vanadium	ppm	0	---	---	---
Silicon	ppm	1	---	---	---



364 - ASCENDUM MACHINERY INC - MACON
4807 HARRISON RD
MACON, GA
US 31206
Contact: ROGER PHILLIPS
ROGER.PHILLIPS@ASCENDUMMACHINERY.COM
T:
F: (478)200-5859

Diagnosis

We recommend drain/flush system. We recommend an early resample to monitor this condition. All metal levels are normal indicating no corrosion in the cooling system. Sample consists almost entirely of free water. Fuel is contaminated with coolant. Moderate concentration of visible dirt/debris present in the fuel. The fuel is no longer serviceable due to the presence of contaminants.

Depot: ASCMAC
Unique No: 10535800
Signed: Jonathan Hester
Report Date: 06 Jul 2023



CONSTRUCTION EQUIPMENT



GRAPHS

Pensky-Martens Flash Point (°C)

