



CONSTRUCTION EQUIPMENT

ALTA RENTS VOLVO A25G 752 137 - TRANSMISSION (AUTO)



Sample No: VCP425276
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No: ALTA RENTS



SAMPLE INFORMATION

Sample Number	VCP425276	---	---	---
Sample Date	26 Jun 2023	---	---	---
Machine Hours	2899	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
 9601 BOGGY CREEK RD
 ORLANDO, FL
 US 32824
 Contact: BRAD BYRO
 bradley.byro@altg.com
 T:
 F: (407)659-8720



OIL CONDITION

Visc @ 40°C	cSt	█ 29.1	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 19	---	---	---
Sodium	ppm	█ <1	---	---	---
Potassium	ppm	█ 8	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 8	---	---	---
Copper	ppm	█ 5	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	█ 0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ <1	---	---	---
Vanadium	ppm	█ 0	---	---	---



ADDITIVES

Calcium	ppm	█ 77	---	---	---
Magnesium	ppm	█ 2	---	---	---
Zinc	ppm	█ 10	---	---	---
Phosphorus	ppm	█ 185	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 89	---	---	---

Depot: VOLVO0096
Unique No: 10537497
Signed: Wes Davis
Report Date: 02 Jul 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

