



CONSTRUCTION EQUIPMENT

VOLVO L150H 6359 - COOLANT



Sample No: VCP408308
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No:



SAMPLE INFORMATION

Sample Number	VCP408308	---	---	---
Sample Date	27 Jun 2023	---	---	---
Machine Hours	6537	---	---	---
Sample Status	NORMAL	---	---	---

McClung-Logan Virginia LLC
 4112 HOLLAND BLVD
 CHESAPEAKE, VA
 US 23323
 Contact: TOMMY GRIFFIN
 tgriffin@mcclung-logan.com
 T: (757)485-3314
 F: (757)485-3415



COOLANT CONDITION

pH	Scale 0-14	7.16	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	---	---	---
Percentage Glycol	%	47.8	---	---	---
Freezing Point	°C	-28	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: VOLVO0264
Unique No: 10538083
Signed: Jonathan Hester
Report Date: 06 Jul 2023




CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

