



# CONSTRUCTION EQUIPMENT

## VOLVO L70H 62421 - TRANSMISSION



**Sample No:** VCP416570

**Oil Type:** NOT GIVEN

**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP416570	---	---	---
Sample Date	01 Jun 2023	---	---	---
Machine Hours	5012	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

**ROMCO INC MAIN**

PO BOX 200210  
SAN ANTONIO, TX  
US 78220

Contact: ALLEN MCALLISTER  
amcallister@romco.com  
T: (800)966-4601  
F: (210)648-7712



### OIL CONDITION

Visc @ 40°C	cSt	█ 35.9	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Silicon	ppm	█ 5	---	---	---
Sodium	ppm	█ <1	---	---	---
Potassium	ppm	█ <1	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



### WEAR METALS

Iron	ppm	█ 2	---	---	---
Copper	ppm	█ 0	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	<1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	<1	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	62	---	---	---
Magnesium	ppm	2	---	---	---
Zinc	ppm	18	---	---	---
Phosphorus	ppm	254	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	118	---	---	---

**Depot:** VOLVO0170  
**Unique No:** 10538601  
**Signed:** Don Baldrige  
**Report Date:** 04 Jul 2023



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron (ppm)




### Lead (ppm)




### Aluminum (ppm)




### Chromium (ppm)



### Copper (ppm)



### Silicon (ppm)



### Viscosity @ 40°C



### Additives

