



# CONSTRUCTION EQUIPMENT

567315 MOTOR CITY VOLVO L220H 3365 - TRANSMISSION (AUTO)



**Sample No:** VCP402386  
**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102  
**Job No:** 567315 MOTOR CITY



## SAMPLE INFORMATION

Sample Number	VCP402386	---	---	---
Sample Date	29 Jun 2023	---	---	---
Machine Hours	1996	---	---	---
Oil Hours	1996	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA EQUIPMENT COMPANY - METRO WEST**  
56195 PONTIAC TRAIL  
NEW HUDSON, MI  
US 48165  
Contact: PAUL CONZ  
paul.conz@altg.com  
T:  
F: (248)356-2029



## OIL CONDITION

Visc @ 40°C	cSt	█ 27.7	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	█ 10	---	---	---
Sodium	ppm	█ 3	---	---	---
Potassium	ppm	█ 2	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



## WEAR METALS

Iron	ppm	█ 100	---	---	---
Copper	ppm	█ 9	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 4	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	█ 0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 6	---	---	---
Vanadium	ppm	█ 0	---	---	---



## ADDITIVES

Calcium	ppm	█ 78	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 13	---	---	---
Phosphorus	ppm	█ 199	---	---	---
Barium	ppm	█ <1	---	---	---
Boron	ppm	█ 80	---	---	---

**Depot:** VOLVO2990  
**Unique No:** 10546444  
**Signed:** Wes Davis  
**Report Date:** 06 Jul 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

