

## CONSTRUCTION EQUIPMENT 3982HR VOLVO L180H 4673 - DIESEL FUEL



Sample No: VCP405758
Oil Type: NOT GIVEN
Job No: 3982HR

SAMPL	E INFORMATIO	N		
Sample Number		VCP405758	 	
Sample Date		29 Jun 2023	 	
Machine Hours		10516	 	
Sample Status		NORMAL	 	
VOLVO	ONDITION			
_	UNDITION			
Sulfur	ppm	■0	 	
Visc @ 40°C	cSt	<b>2.53</b>	 	
CUNTA	MINATION			
_				
Water	%	■ 0.002	 	
Lead	ppm	<b>■&lt;1</b>	 	
Nickel	ppm	<b>0</b>	 	
Aluminum	ppm	<b>■</b> 0	 	
Vanadium	ppm	0	 	
Silicon	ppm	<b>■</b> 0	 	



## **HIGHWAY EQUIPMENT & SUPPLY CO MAIN**

PO BOX 1957 HARRISBURG, PA US 17105 Contact: BRANDON MIDDAUGH bmiddaugh@hwyequip.com T·

F: (717)564-3568

## Diagnosis

This is a baseline read-out on the submitted sample. No corrective action is recommended at this time. All metal levels are normal indicating no corrosion in the cooling system. The water content is negligible. No coolant detected in the sample. There is no indication of any contamination in the fuel. The condition of the fuel is acceptable for the time in service.

Depot:VOLVO0025Unique No:10546494Signed:Jonathan HesterReport Date:07 Jul 2023



## **CONSTRUCTION EQUIPMENT**





