

# CONSTRUCTION EQUIPMENT VOLVO A40G 352778 - DIESEL ENGINE



Sample No: VCP415814

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No:

VOLVO					
SAMPLE II	NFORMATION				
Sample Number		VCP415814	VCP344076	VCP328956	
Sample Date		29 Jun 2023	21 Jan 2022	15 Oct 2021	
Machine Hours		3734	0	585	
Oil Hours		0	0	0	
Oil Changed		Changed	Changed	Changed	
Sample Status		ABNORMAL	NORMAL	ATTENTION	
OIL CONDITION					
Visc @ 100°C	cSt	<u>^</u> 12.3	<b>□</b> 12.5	<u>▲</u> 10.7	
Base Number (BN)		<b>1.8</b>	10.2		
Oxidation (PA)	%	104	86	65	
CONTAMINATION					
		=0.6	<b>5</b> 03		
Soot %	%	<b>■</b> 0.6 108	□ 0.2 73	□ 0.2 65	
Nitration (PA) Sulfation (PA)	%	74	66	58	
Glycol	%	NEG	NEG	NEG	
Fuel	%	<1.0	<1.0	□ 0.8	
Silicon	ppm	₹1.0	8	□ 0.8 □ 25	
Sodium	ppm	■4	<b>2</b>	1	
Potassium	ppm	<b>2</b>	0	2	
	ρρ				
WEAR METALS					
_					
Iron	ppm	<b>26</b>	10	<b>1</b> 9	
Copper	ppm	<u>^</u> 66	7	□37	
Lead Tin	ppm	<b>2</b>	<1	<b>2</b>	
Aluminum	ppm	<b>■3</b>	1 1	<b>■</b> 4	
Chromium	ppm	<b>=</b> <1	<1	■ <1	
Molybdenum	ppm	<b>1</b> 49	<b>□</b> 48	<b>□</b> 61	
Nickel	ppm	<b>9</b>	<1	■ <1	
Titanium	ppm	0	<1	<1	
Silver	ppm	■0	<1	<1	
Manganese	ppm	<b>2</b>	<b>-</b> <1	<b>2</b>	
Vanadium	ppm	0	0	0	
ADDITIVES					
Calcium	ppm	<b>1759</b>	□1708	■ 1746	
Magnesium	ppm	<b>■512</b>	<b>463</b>	■373	
Zinc	ppm	■1116	■1099	■1198	
Phosphorus	ppm	■835	■912	■1028	
Barium	ppm	■0	□0	<b>   &lt;1</b>	
Boron	ppm	<b>6</b>	■38	<b>□</b> 66	



#### **ALTA EQUIPMENT COMPANY**

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com

F: (239)481-3302

### Diagnosis

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core). All other component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.

Depot:VOLVO0090Unique No:10546912Signed:Sean FeltonReport Date:07 Jul 2023



## **CONSTRUCTION EQUIPMENT**





