

## CONSTRUCTION EQUIPMENT VOLVO L220H 2890 - HYDRAULIC SYSTEM



Sample No: VCP408109

**Oil Type:** AW HYDRAULIC OIL ISO 46

Job No:

	NFORMATION		 	
	NF UNMATION		 	
Sample Number		VCP408109	 	
Sample Date		05 Jul 2023	 	
Machine Hours		10844	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
VOLVO				
VIL COND	ITION			
Visc @ 40°C	cSt	43.6	 	
Acid Number (AN)		0.36	 	
	5 , 5			
CONTAM				
CONTAMI	NATION			
Particles >4µm		2397	 	
Particles >6µm		620	 	
Particles >14µm		<b>70</b>	 	
SO 4406:1999 (c)		18/16/13	 	
Silicon	ppm	∎1	 	
Sodium	ppm	<b>4</b>	 	
Potassium	ppm	<b>1</b>	 	
VOLVO				
🤍 WEAR ME	TALS			
ron	ppm	5	 	
Copper	ppm	<b>1</b>	 	
Lead	ppm	0	 	
Tin	ppm	□<1	 	
Aluminum	ppm		 	
Chromium	ppm	2	 	
Molybdenum	ppm	<b>□</b> <1	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	<1	 	
	18 19			
VOLVO	e			
V ADDITIVE	.2			
Calcium	ppm	51	 	
Magnesium	ppm	3	 	
Zinc	ppm	<b>402</b>	 	
Phosphorus	ppm	336	 	
		■ <1	 	
Barium	ppm	<u> </u>		



## ο ΙΝΟ

E LOOP 820 VORTH, TX 106 t: CHRIS BITNER @romco.com 626-8983

## nosis

ple at the next service interval nitor. The fluid was not ed, however, a fluid match es that this fluid is (GENERIC) /DRAULIC OIL ISO 46. Please n.

nponent wear rates are normal. stem cleanliness is acceptable ur target ISO 4406 cleanliness The system and fluid ness is acceptable. The AN acceptable for this fluid. The ion of the oil is suitable for service.

Depot:	VOLVO0081		
Unique No:	10547065		
Signed:	Wes Davis		
Report Date:	07 Jul 2023		

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO

